

# GX-Force Quick Reference Guide

**Turn On**

Press & Hold

**POWER  
MODE**


**Past Due Bump/CAL**

To Bump / CAL

**POWER  
MODE**


Confirm & Use

**AIR**



**Normal  
Operation**

After brief  
warm-up period



**Fresh Air**

Press & Hold


**AIR**

**Turn Off**

Press & Hold

**POWER  
MODE**

# GX-Force Quick Reference Guide



Scan QR code for  
GX-Force Manual

RKI Instruments, Inc. 33248 Central Ave, Union City, CA 94587

Phone (510) 441-5656 • (800) 754-5165 • [www.rkiinstruments.com](http://www.rkiinstruments.com)

230511/10000

