



# HYDROflash FR Foul Weather Jacket - Fluorescent Yellow



## Specs

Product Code HYDROFLASHJ-Y-\_\_

Sizes SM-3X | Other sizes available upon request

Made To Order Colors 

Fabric / Material GORE-TEX PYRAD® Polyester on PTFE & DuPont™ Nomex® Knit

# Compliance

---

Arc Rating 30 cal/cm<sup>2</sup>

CAT Level CAT 3

ANSI Type / Class Type R Class 3

Standards

- ANSI/ISEA 107 Type R Class 3
- ASTM F2733
- ASTM F1891
- CSA Z462
- ASTM F903
- OSHA 1910.269
- Gas Probe Shirley Method 138:2000, EN 1149-3/2004 & EN 1149-5/2008
- CSA Z96 Class 2

# Features

---

Features

- HYDROFlash FR™ (2 Layer PYRAD) is the lightest weight waterproof, breathable Flash Fire rated garment available
- Lightweight, breathable, and fast drying
- 100% waterproof and windproof
- Resists cold cracking in low temperatures
- Hot liquid and steam resistant
- Petroleum and oil-based mud resistant
- 3M™ Scotchlite™ FR silver segmented reflective trim
- Hook and loop straps at cuffs
- Jacket hood sold separately
- Jacket has zippered chest pocket and two lower hand warmer pockets
- Jacket has 2 mic/gas detector tabs
- Jacket with Bib ensembles are Compliant to CSA Z96 Class 3
- Made in the USA

## Product Care

---

Product Care

- READ THE GARMENT LABEL AND LAUNDRY PER INSTRUCTIONS ON GARMENT LABEL.
- DO NOT use bleach or hydrogen peroxide. DO NOT use fabric softeners.
- Wash/Laundry Instructions: Wash separately from other garments. Machine wash warm (max. 120°F/50°C) using mild detergent. Rinse 4 times (adding extra rinse to standard 3-rinse cycle) to remove all soil and detergent residues. Dawn Dish Liquid is recommended for oil based stains. Pre-treat the area, soak for stubborn stains or mild stain treatments may be used. Ensure the product is completely rinsed from the fabric before drying.
- Drying: Turn garment inside out before drying. Tumble dry using permanent press setting (medium). Tumble drying is recommended to protect garment's water repellent treatment.
- Wash according to the instructions above to remove any contaminants in order to maintain fabric performance when garment becomes soiled with dirt, greases, oils, etc.
- If contaminants cannot be removed after laundering, it is best to discontinue use of garment.

## Sizing Chart

---

HYDROflash FR™ Jacket			
Size	Neck	Chest	Arm Length - Regular
SM	14" - 14.5"	34" - 36"	31" - 31 1/4"
MD	15" - 15.5"	38" - 40"	32 1/4" - 33"
LG	16" - 16.5"	42" - 44"	33 1/2" - 34 1/4"
XL	17" - 17.5"	46" - 48"	34 3/4" - 35 1/2"
2X	18" - 18.5"	50" - 52"	36" - 36 3/4"
3X	19" - 19.5"	54" - 56"	37 1/4" - 38"