


HYDROflash FR Foul Weather Jacket - Navy















Specs

Product Code	HYDROFLASHJ-N
Sizes	SM-3X Other sizes available upon request
Made To Order Colors	
Fabric / Material	GORE-TEX PYRAD® Polyester on PTFE & DuPont™ Nomex® Knit

Compliance

Arc Rating	15 cal/cm ²
CAT Level	CAT 2
Standards	 ASTM F2733 ASTM F1891 CSA Z462 ASTM F903 OSHA 1910.269 Gas Probe Shirley Method 138:2000, EN 1149-3/2004 & EN 1149-5/2008 CSA Z96 Class 2

Features

 100% waterproof and windproof Resists cold cracking in low temperatures Hot liquid and steam resistant Petroleum and oil-based mud resistant 3M™ Scotchlite™ FR silver segmented reflective trim Hook and loop straps at cuffs 		 HYDROFlash FR™ (2 Layer PYRAD) is the lightest weight waterproof, breathable Flash Fire rated garment available Lightweight, breathable, and fast drying
 Jacket hood sold separately Jacket has zippered chest pocket and two lower hand warmer pockets Jacket has 2 mic/gas detector tabs Jacket with Bib ensembles are Compliant to CSA Z96 Class 3 Made in the USA 	Features	 100% waterproof and windproof Resists cold cracking in low temperatures Hot liquid and steam resistant Petroleum and oil-based mud resistant 3M™ Scotchlite™ FR silver segmented reflective trim Hook and loop straps at cuffs Jacket hood sold separately Jacket has zippered chest pocket and two lower hand warmer pockets Jacket has 2 mic/gas detector tabs Jacket with Bib ensembles are Compliant to CSA Z96 Class 3

Product Care

- READ THE GARMENT LABEL AND LAUNDER PER INSTRUCTIONS ON GARMENT LABEL.
- DO NOT use bleach or hydrogen peroxide. DO NOT use fabric softeners.
- Wash/Laundering Instructions: Wash separately from other garments. Machine wash warm (max. 120°F/50°C) using mild detergent. Rinse 4 times (adding extra rinse to standard 3-rinse cycle) to remove all soil and detergent residues. Dawn Dish Liquid is recommended for oil based stains. Pre-treat the area, soak for stubborn stains or mild stain treatments may be used. Ensure the product is completely rinsed from the fabric before drying.
- Drying: Turn garment inside out before drying. Tumble dry using permanent press setting (medium). Tumble drying is recommended to protect garment's water repellent treatment.
- Wash according to the instructions above to remove any contaminants in order to maintain fabric performance when garment becomes soiled with dirt, greases, oils, etc.
- If contaminants cannot be removed after laundering, it is best to discontinue use of garment.

Sizing Chart

Size	Neck	Chest	Arm Length - Regula
SM	14" - 14.5"	34" - 36"	31' - 31 1/4"
MD	15" - 15.5"	38" - 40"	32 1/4" - 33"
LG	16" - 16.5"	42" - 44"	33 1/2" - 34 1/4"
XL	17" - 17.5"	46" - 48"	34 3/4" - 35 1/2"
2X	18" - 18.5"	50" - 52"	36" - 36 3/4"
3X	19" - 19.5"	54" - 56"	37 1/4" - 38"

Product Care